

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start		Rating **	A	Issue No.	16
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_LD0003_01_s_2013_16				
Comment Code					
Inspector Comment					
The LMA has the O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	17
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment			°	°
				°	°
DWR ID	DWR_LD0003_01_s_2013_17				
Comment Code					
Inspector Comment					
The LMA has adequate flood fight supplies and equipment.					

No Photos

LM Start		Rating **	A	Issue No.	18
LM End		Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_LD0003_01_s_2013_18				
Comment Code					
Inspector Comment					
The LMA has completed flood fight training in the past.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	0.56	Rating **	M	Issue No.	23
LM End	0.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.389390 °	39.389219 °
				-121.995539 °	-121.996854 °
DWR ID	DWR_LD0003_01_s_2012_23				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

LM Start	0.69	Rating **	M	Issue No.	55
LM End	0.69	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.388716 °	39.388716 °
				-121.997774 °	-121.997774 °
DWR ID	DWR_LD0003_01_s_2014_55				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_55_20160324_00032.jpg



View of the rodent activity along the w/s slope.

LM Start	0.71	Rating **	U	Issue No.	3
LM End	0.75	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.388578 °	39.388323 °
				-121.997987 °	-121.998727 °
DWR ID	DWR_LD0003_01_s_2012_3				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_3_20160324_00001.jpg



View of squirrel holes along the slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	0.78	Rating **	M	Issue No.	44
LM End	0.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.388440 °	39.388440 °
				-121.999175 °	-121.999175 °
DWR ID	DWR_LD0003_01_f_2015_44				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the waterside slope damage caused by vehicle traffic.					

Photo 1 of 1 : SP_2016_LD0003_27_44_20160324_00023.jpg



View of the vehicle erosion along the waterside slope.

LM Start	0.79	Rating **	M	Issue No.	49
LM End	0.79	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.388508 °	39.388508 °
				-121.999407 °	-121.999407 °
DWR ID	DWR_LD0003_01_f_2015_49				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the landside slope damaged by vehicle traffic.					

Photo 1 of 1 : SP_2016_LD0003_27_49_20160324_00026.jpg



View of the landside slope erosion caused by vehicle traffic.

LM Start	0.81	Rating **	U	Issue No.	51
LM End	0.91	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.388690 °	39.389867 °
				-121.999820 °	-122.000585 °
DWR ID	DWR_LD0003_01_f_2015_51				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_51_20160324_00029.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	0.82	Rating **	M	Issue No.	67
LM End	0.82	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.388725 °	39.388725 °
				-121.999870 °	-121.999870 °
DWR ID	DWR_LD0003_01_f_2013_67				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

LM Start	1.21	Rating **	M	Issue No.	52
LM End	1.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.394010 °	39.394010 °
				-122.000977 °	-122.000977 °
DWR ID	DWR_LD0003_01_f_2015_52				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_52_20160324_00030.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	1.35	Rating **	A/W	Issue No.	8
LM End	1.62	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.395982 °	39.399959 °
				-122.002451 °	-122.003522 °
DWR ID	DWR_LD0003_01_s_2016_8				
Comment Code					
Inspector Comment					
2000 - Snags along toe at downstream end; slow erosion. 2001 - A couple of small fresh slumps in the lower bank section. 2006 - Some minor new erosion at the downstream end. 2009 - Some new erosion. 2010 - New toe erosion. 2011 - Minor new erosion. 2012 - Minor new erosion at the toe. 2013 - Site removed because sufficient berm width, does not meet criteria. 2015: [2015 Site ID: SAC_163-0_L]					

No Photos

LM Start	1.73	Rating **	U	Issue No.	15
LM End	2.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.401452 °	39.406557 °
				-122.002132 °	-121.995052 °
DWR ID	DWR_LD0003_01_s_2012_15				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_15_20160324_00012.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	1.78	Rating **	U	Issue No.	13
LM End	2.52	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.402115 °	39.407248 °
				-122.002047 °	-121.993177 °
DWR ID	DWR_LD0003_01_s_2012_13				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_13_20160324_00010.jpg



View of the rodent holes along the waterside slope.

LM Start	2.57	Rating **	U	Issue No.	47
LM End	2.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.407582 °	39.407582 °
				-121.992417 °	-121.992417 °
DWR ID	DWR_LD0003_01_f_2015_47				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent hole on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_47_20160324_00024.jpg



View of the rodent holes along the landside slope.

LM Start	2.96	Rating **	U	Issue No.	54
LM End	3.09	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.412613 °	39.414392 °
				-121.991278 °	-121.992257 °
DWR ID	DWR_LD0003_01_f_2015_54				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Implement rodent control measures and repair rodent damage on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_54_20160324_00031.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	3.39	Rating **	M	Issue No.	9
LM End	3.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.418382 °	39.418382 °
				-121.992480 °	-121.992480 °
DWR ID	DWR_LD0003_01_s_2012_9				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the erosion along the landside slope and prevent vehicle access					

Photo 1 of 1 : SP_2016_LD0003_27_9_20160324_00005.jpg



View of the vehicle erosion along the landside slope.

LM Start	3.41	Rating **	U	Issue No.	58
LM End	3.48	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.418687 °	39.419762 °
				-121.992422 °	-121.992307 °
DWR ID	DWR_LD0003_01_f_2015_58				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Implement rodent control measures and repair rodent damage on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_58_20160324_00034.jpg



View of the rodent. Holes along the landside slope.

LM Start	3.76	Rating **	M	Issue No.	19
LM End	3.76	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.423747 °	39.423747 °
				-121.991667 °	-121.991667 °
DWR ID	DWR_LD0003_01_s_2012_19				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair the vehicle erosion on the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_19_20160324_00013.jpg



View of the vehicle erosion along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	3.88	Rating **	U	Issue No.	59
LM End	3.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.425162 °	39.425162 °
				-121.990528 °	-121.990528 °
DWR ID	DWR_LD0003_01_f_2015_59				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_59_20160324_00035.jpg



View of the rodent holes along the landside slope.

LM Start	4.33	Rating **	M	Issue No.	66
LM End	4.33	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.430927 °	39.430927 °
				-121.987142 °	-121.987142 °
DWR ID	DWR_LD0003_01_f_2015_66				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from LS toe.					

Photo 1 of 1 : SP_2016_LD0003_27_66_20160324_00041.jpg



View of the prunings along the landside toe.

LM Start	4.63	Rating **	U	Issue No.	64
LM End	4.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.435205 °	39.435855 °
				-121.988097 °	-121.988252 °
DWR ID	DWR_LD0003_01_f_2013_64				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Implement rodent control measures and repair rodent damage on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_64_20160324_00040.jpg



View of the rodent activity along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	4.66	Rating **	M	Issue No.	63
LM End	4.66	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.435701 °	39.435701 °
				-121.988189 °	-121.988189 °
DWR ID	DWR_LD0003_01_f_2013_63				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_63_20160324_00039.jpg



View of the prunings along the landside toe.

LM Start	4.68	Rating **	M	Issue No.	2
LM End	4.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.435907 °	39.435907 °
				-121.988242 °	-121.988242 °
DWR ID	DWR_LD0003_01_f_2013_2				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
tire ruts land and water sides					

No Photos

LM Start	5.06	Rating **	M	Issue No.	69
LM End	5.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.441057 °	39.441057 °
				-121.990458 °	-121.990458 °
DWR ID	DWR_LD0003_01_f_2015_69				
Comment Code					
PR : Prunings					
Inspector Comment					
Remove prunings from LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_69_20160324_00044.jpg



View of the prunings along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	5.06	Rating **	U	Issue No.	21
LM End	5.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.441128 °	39.443793 °
				-121.990475 °	-121.991297 °
DWR ID	DWR_LD0003_01_f_2015_21				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Remove the rodent holes along the landside slope.					

LM Start	5.06	Rating **	U	Issue No.	21 (cont)
LM End	5.25	Issue Type +	Ma	Location *	LS

Photo 1 of 2 : SP_2016_LD0003_27_21_20160324_00014.jpg



View of no rodent activity.

Photo 2 of 2 : SP_2016_LD0003_27_21_20160324_00015.jpg



View of the rodent holes along the landside slope.

LM Start	5.39	Rating **	U	Issue No.	70
LM End	5.39	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.445808 °	39.445808 °
				-121.991552 °	-121.991552 °
DWR ID	DWR_LD0003_01_f_2015_70				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Remove the rodent holes along the landside slope.					

Photo 1 of 1 : SP_2016_LD0003_27_70_20160324_00045.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	5.53	Rating **	U	Issue No.	62
LM End	5.62	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.447900 °	39.449115 °
				-121.991748 °	-121.991873 °
DWR ID	DWR_LD0003_01_f_2013_62				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_62_20160324_00038.jpg



View of the rodent holes along the landside slope.

LM Start	5.77	Rating **	M	Issue No.	25
LM End	5.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.451293 °	39.452872 °
				-121.992370 °	-121.992897 °
DWR ID	DWR_LD0003_01_s_2012_25				
Comment Code					
AV : Abandoned vehicles					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_25_20160324_00016.jpg



View of the equipment along the L/S toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	6.02	Rating **	M	Issue No.	11
LM End	6.05	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.454696 °	39.455096 °
				-121.994107 °	-121.994217 °
DWR ID	DWR_LD0003_01_s _ 2016_11				
Comment Code					
Inspector Comment					
1997 - Erosion of top left bank; eroding downstream of rock section where levee is closest to the bank, approximately 40 to 50 ft of bank retreat, some berm left. 1999 - Some new beach sedimentation at toe. 2000 - Snags in eddy area could induce bank erosion at higher flows. 2002 - Small bar is gone. 2003 - Bar is present and higher. 2004 - Some new deposition on the bank at the upstream end. 2006 - New sand on bar and bank. 2007 - New sand deposition with vegetation colonizing bars between dikes. 2008 - More eddy sedimentation and vegetation on bar along bank. Bank is healing due to retreat of right bank. 2009 - Additional bar sedimentation. 2010 - some deposition at toe, new erosion on opposite bank. Site continues to heal. 2012 - Majority of site healed but upstream end still needs toe rock. 2015: Last observed in 2013. [2015 Site ID: SAC 168-3 L]					

No Photos

LM Start	6.06	Rating **	U	Issue No.	71
LM End	6.06	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.455313 °	39.455313 °
				-121.993712 °	-121.993712 °
DWR ID	DWR_LD0003_01_f_2015_71				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent damage on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_71_20160324_00046.jpg



View of the rodent holes along the landside slope.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	6.11	Rating **	U	Issue No.	72
LM End	6.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.456018 °	39.456018 °
				-121.993772 °	-121.993772 °
DWR ID	DWR_LD0003_01_f_2015_72				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent damage on LS slope					

Photo 1 of 1 : SP_2016_LD0003_27_72_20160324_00047.jpg



View of the rodent holes along the landside slope.

LM Start	6.24	Rating **	M	Issue No.	7
LM End	6.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.457968 °	39.459955 °
				-121.993712 °	-121.993512 °
DWR ID	DWR_LD0003_01_s_2012_7				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_7_20160324_00004.jpg



Trim the trees 5 feet for better visibility.

LM Start	6.29	Rating **	M	Issue No.	48
LM End	6.38	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.458587 °	39.459912 °
				-121.993777 °	-121.993592 °
DWR ID	DWR_LD0003_01_s_2012_48				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_48_20160324_00025.jpg



Trim the trees up 5 feet for better visibility.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	6.50	Rating **	M	Issue No.	84
LM End	6.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.461610 °	39.461610 °
				-121.992950 °	-121.992950 °
DWR ID	DWR_LD0003_01_s_2016_84				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

No Photos

LM Start	6.57	Rating **	M	Issue No.	34
LM End	6.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.462505 °	39.462505 °
				-121.992698 °	-121.992698 °
DWR ID	DWR_LD0003_01_s_2012_34				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Repair damage to levee caused by driveway.					

No Photos

LM Start	6.61	Rating **	U	Issue No.	76
LM End	6.61	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.463185 °	39.463185 °
				-121.992657 °	-121.992657 °
DWR ID	DWR_LD0003_01_f_2015_76				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					
Repair the burned out stump hole along the landside toe.					

Photo 1 of 1 : SP_2016_LD0003_27_76_20160324_00051.jpg



View of the burned out stump hole along the landside toe.

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	6.63	Rating **	M	Issue No.	12
LM End	6.63	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.463366 °	39.463366 °
				-121.992586 °	-121.992586 °
DWR ID	DWR_LD0003_01_f_2012_12				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Building has burned down.					

Photo 1 of 1 : SP_2016_LD0003_27_12_20160324_00009.jpg



View of concrete stairs & foundation along the slope of the levee.

LM Start	6.75	Rating **	M	Issue No.	35
LM End	6.75	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.465013 °	39.465013 °
				-121.991455 °	-121.991455 °
DWR ID	DWR_LD0003_01_s_2012_35				
Comment Code					
T1 : Trim trees to at least five feet above ground level.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_35_20160324_00019.jpg



View of the trees that are hanging over the landside slope of the levee.

LM Start	7.21	Rating **	M	Issue No.	14
LM End	7.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.471658 °	39.471658 °
				-121.991245 °	-121.991245 °
DWR ID	DWR_LD0003_01_s_2012_14				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_14_20160324_00011.jpg



Vehicle erosion along the slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	7.68	Rating **	M	Issue No.	60
LM End	7.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			39.478464 °	39.478464 °
				-121.990686 °	-121.990686 °
DWR ID	DWR_LD0003_01_f_2013_60				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_60_20160324_00036.jpg



View of the prunings along the landside toe.

LM Start	9.23	Rating **	M	Issue No.	78
LM End	9.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.498897 °	39.498897 °
				-121.986827 °	-121.986827 °
DWR ID	DWR_LD0003_01_f_2015_78				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent hole on LS shoulder.					

Photo 1 of 1 : SP_2016_LD0003_27_78_20160324_00053.jpg



View of the rodent holes along the landside slope.

LM Start	9.50	Rating **	U	Issue No.	79
LM End	9.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.502698 °	39.502698 °
				-121.985235 °	-121.985235 °
DWR ID	DWR_LD0003_01_f_2015_79				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Repair rodent damage on LS slope.					

Photo 1 of 1 : SP_2016_LD0003_27_79_20160324_00054.jpg



View of the rodent holes along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	9.61	Rating **	M	Issue No.	10
LM End	9.88	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.504388 °	39.508117 °
				-121.985301 °	-121.986562 °
DWR ID	DWR LD0003 01 s 2016 10				

Comment Code

Inspector Comment

2007 - Getting close to the levee. Bank is clayey silt with clayey/silty toe. 2008 - Looks a little worse at the upstream end. 2009 - Some new erosion and slumping. 2010 - Some new erosion upstream of site, actively eroding at low flow. New bank swallow colony noted. 2011 - Significant erosion since last year, with an estimated 10 to 15 feet of berm lost. Large sections of the bank have slumped off. 2012 - Part of the site appears to be stabilizing, but still minor slumping in other locations. 2013 - Minor new erosion at toe. 2015: Last observed in 2013. [2015 Site ID: SAC_172-0_L] On 3/25/2016, recent high water caused river to erode to within 10-20 feet of levee toe. Appears still somewhat active.

LM Start	9.61	Rating **	M	Issue No.	10 (cont)
LM End	9.88	Issue Type +	Ma	Location *	WS

Photo 1 of 3 : SP_2016_LD0003_27_10_20160324_00006.jpg



USACE 2013 Photo #1

Photo 2 of 3 : SP_2016_LD0003_27_10_20160324_00007.jpg



USACE 2013 Photo #2

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	9.61	Rating **	M	Issue No.	10 (cont)
LM End	9.88	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2015 USACE Erosion Survey, DRAFT			39.504388 °	39.508117 °
				-121.985301 °	-121.986562 °
DWR ID	DWR_LD0003_01_s_2016_10				
Comment Code					
Inspector Comment					
2007 - Getting close to the levee. Bank is clayey silt with clayey/silty toe. 2008 - Looks a little worse at the upstream end. 2009 - Some new erosion and slumping. 2010 - Some new erosion upstream of site, actively eroding at low flow. New bank swallow colony noted. 2011 - Significant erosion since last year, with an estimated 10 to 15 feet of berm lost. Large sections of the bank have slumped off. 2012 - Part of the site appears to be stabilizing, but still minor slumping in other locations. 2013 - Minor new erosion at toe. 2015: Last observed in 2013. [2015 Site ID: SAC_172-0_L] On 3/25/2016, recent high water caused river to erode to within 10-20 feet of levee toe. Appears still somewhat active.					

Photo 3 of 3 : SP_2016_LD0003_27_10_20160324_00008.jpg



USACE 2013 Photo #3

LM Start	9.64	Rating **	U	Issue No.	80
LM End	9.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.504682 °	39.508065 °
				-121.984465 °	-121.984030 °
DWR ID	DWR_LD0003_01_f_2015_80				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Clear vegetation from levee slopes.					

Photo 1 of 1 : SP_2016_LD0003_27_80_20160324_00055.jpg



View of the vegetation along the waterside slope and toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	9.67	Rating **	U	Issue No.	81
LM End	9.87	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.505072 °	39.507965 °
				-121.984302 °	-121.984047 °
DWR ID	DWR_LD0003_01_f_2015_81				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Clear vegetation from levee slopes.					

Photo 1 of 1 : SP_2016_LD0003_27_81_20160324_00056.jpg



View of the vegetation along the landside slope.

LM Start	9.70	Rating **	U	Issue No.	50
LM End	9.70	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.505435 °	39.505435 °
				-121.984172 °	-121.984172 °
DWR ID	DWR_LD0003_01_f_2014_50				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Repair the erosion along the waterside toe. On 3/25/2016, recent high water caused river to erode to within 10-20 feet of levee toe. Appears still somewhat active.					

Photo 1 of 4 : SP_2016_LD0003_27_50_20160324_00027.jpg



View of erosion along the waterside toe. Same site as the USACE erosion issue.

LM Start	9.70	Rating **	U	Issue No.	50 (cont)
LM End	9.70	Issue Type +	Ma	Location *	WS

Photo 2 of 4 : SP_2016_LD0003_27_50_20160411_00101.jpg



View of erosion along the waterside toe. Same site as the USACE erosion issue. Photo 3/25/2016

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	9.70	Rating **	U	Issue No.	50 (cont)	
LM End	9.70	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			39.505435 °	39.505435 °	
				-121.984172 °	-121.984172 °	
DWR ID	DWR_LD0003_01_f_2014_50					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
Repair the erosion along the waterside toe. On 3/25/2016, recent high water caused river to erode to within 10-20 feet of levee toe. Appears still somewhat active.						

Photo 3 of 4 : SP_2016_LD0003_27_50_20160411_00103.jpg



View of erosion along the waterside toe, downstream. Same site as the USACE erosion issue. Photo 3/25/2016

LM Start	9.70	Rating **	U	Issue No.	50 (cont)
LM End	9.70	Issue Type +	Ma	Location *	WS

Photo 4 of 4 : SP_2016_LD0003_27_50_20160324_00028.jpg



View of the erosion along the waterside toe. Same site as the USACE erosion issue.

LM Start	10.11	Rating **	M	Issue No.	87
LM End	10.11	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.511450 °	39.511450 °
				-121.983930 °	-121.983930 °
DWR ID	DWR_LD0003_01_s_2016_87				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					
Repair water erosion rut on L/S slope.					

Photo 1 of 1 : SP_2016_LD0003_27_87_20160405_00100.jpg



Erosion ruts on l/s slope

* Location		** Rating		+ Issue Type	
LS : Land Side	N/A : Not Applicable	A : Acceptable	N : Not Inspected/Rated	Ma : Maintenance Deficiency	
WS : Water Side		M : Minimally Acceptable	C : Corrected	Ob : Design & System Obsolescence	
CR : Crown		U : Unacceptable	A/W : Acceptable but Monitor & Maintain	En : Enforcement	

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	10.14	Rating **	M	Issue No.	5
LM End	10.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.511788 °	39.512395 °
				-121.983750 °	-121.981975 °
DWR ID	DWR_LD0003_01_s_2012_5				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					

No Photos

LM Start	10.50	Rating **	N	Issue No.	29	
LM End	10.50	Issue Type +	Ma	Location *	WS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Trim / Thin Trees			39.515342 °		39.515342 °
				-121.979202 °		-121.979202 °
DWR ID	DWR_LD0003_01_s_2012_29					
Comment Code						
T5 : Tree stumps.						
Inspector Comment						

Photo 1 of 1 : SP_2016_LD0003_27_29_20160324_00017.jpg



View of the stump along the toe.

LM Start	10.67	Rating **	N	Issue No.	30
LM End	10.67	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.517715 °	39.517715 °
				-121.979155 °	-121.979155 °
DWR ID	DWR_LD0003_01_s_2012_30				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_30_20160324_00018.jpg



View of the stump along the slope.

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

LM Start	10.81	Rating **	N	Issue No.	82
LM End	10.81	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.519727 °	39.519727 °
				-121.978362 °	-121.978362 °
DWR ID	DWR_LD0003_01_f_2015_82				
Comment Code					
T5 : Tree stumps.					
Inspector Comment					
Remove tree stump from WS toe.					

No Photos

LM Start	10.98	Rating **	U	Issue No.	4
LM End	11.01	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.522058 °	39.522480 °
				-121.979133 °	-121.979200 °
DWR ID	DWR_LD0003_01_s_2012_4				
Comment Code					
T2 : Thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Trim the trees up at least 5 feet to allow visibility. Also two large stumps north of trees.					

Photo 1 of 1 : SP_2016_LD0003_27_4_20160324_00002.jpg



View of the trees along the slope.

LM Start	11.04	Rating **	M	Issue No.	6
LM End	11.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			39.522921 °	39.522921 °
				-121.979172 °	-121.979172 °
DWR ID	DWR_LD0003_01_f_2012_6				
Comment Code					
S1 : Repair slope instability.					
Inspector Comment					

Photo 1 of 1 : SP_2016_LD0003_27_6_20160324_00003.jpg



View of the vertical cut along the w/s toe.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2016

Levee District No. 0003 (Glenn County)

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Glenn County Sacramento River	Left	11.97	03/25/2016 03/25/2016	Keith Millard

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---